

Bruhath Bangalore Mahanagara palike,**Inspection Report**

1	Name of work	Construction of Zym Building Near HMT Ground (J.P.Park) in ward No.17
2	Administration Approval & Date	EE/RRND/AS/123/2015-16 Dtd:29-10-2015 by EE (RRND)
3	Technical Sanction Estimate No.& Date	CE/RRNZ/TS/187/2015-16 Dtd:30-10-2015 by CE (RRNZ)
4	Estimate Amount	Rs.50.00 Lakhs
5	Job Code No.	017-15-000030
6	P-Code	P-3089
7	Agreement No & date	EE/RRND/AGMT/104/2015-16 Dtd.16-01-2016.
8	Work order Number & Date	EE/RRND/Wo No./104/2015-16 Dtd.16-01-2016.
9	Contract Amount as per Agreement	Rs.54,68,651/-
10	Bill Amount	Rs.54,65,453/-
11	B.R. No. & Date	-
12	Agency	Sri.M.Manjunath
13	M.B. Number & Page No. of Measurement records	5682/16-17 Pages No.568101 to 568135
14	Date of Inspection	12/10/2017
15	Enclosures	1)...8... Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site location along with the concerned person, as per EE (RRND) Letter No EE (RRN) 528 / 17-18 dated 11-10-2017. The Items indicated in the MB, which are susceptible for measurements have been checked and found to be satisfactory

EE RRN Division, RR Nagara Zone.

(R.Sathyannarayana)
Inspection Report officer,